Thermocouple Replacement:

This thermocouple replaces all previous types. It is larger than those with a metal housing so you must enlarge the hole through the kiln wall ½".